

Report Date: 25 Apr 2014

**Summary Report for Individual Task
441-096-2439
Emplace the Deployable Rapid Assembly Shelter (DRASH)
Status: Approved**

DISTRIBUTION RESTRICTION: Approved for public release; distribution is unlimited.

DESTRUCTION NOTICE: None

Condition: Location has been secured and the Battery Command Post emplacement must be completed. You have been directed to emplace the Deployable Rapid Assembly Shelter (DRASH) in accordance with local Standard Operating Procedures (SOP). Some iterations of this task should be performed in MOPP 4.

Standard: Emplace the Deployable Rapid Assembly Shelter (DRASH) IAW local SOP and manufacturer's instructions. Ensure all steps are performed without causing injury to crew members or other personnel, with no damage to equipment and minimal damage to the environment.

Special Condition: None

Safety Level: Low

MOPP: Sometimes

Task Statements

Cue: Emplace the Deployable Rapid Assembly Shelter (DRASH).

DANGER
None

WARNING
None

CAUTION
None

Remarks: None

Notes: All required Air Defense specific references and technical manuals will be provided by the local Air Defense Command.

Performance Steps

1. Offload shelter transport bag.
2. Place shelter transport bag close to where shelter will be raised.
Note: Ensure area is fairly level and is cleared of any obstacles that could damage the tent.
3. Open transport bag by loosening the two (2) outside cinch straps and untying the rope.
4. Remove shelter repair kit, push poles and cinched shelter bundle from transport bag.
5. Uncinch the shelter by removing the cinch strap.
6. Unroll the integrated floor from cinched shelter.
7. Place the integrated floor in the desired location (green side up).

WARNING

Use eye protection when driving stakes into the ground.

8. Extend integrated floor and using hammer stake-down floor.
Note: Ensure that the stakes are flush with the ground.
9. Place the bundled DRASH shelter on the center of the integrated floor with the exterior side (green/tan) facing up and interior side (white) facing down.
Note: Ensure that you align the long side of the shelter with the long side of the ground cover.
10. Spread the DRASH shelter.
11. Raise the DRASH shelter.
12. Secure integrated floor to the inner liner.

WARNING

Use eye protection when driving stakes into the ground.

13. Secure the shelter by staking down all the wind lines.

(Asterisks indicates a leader performance step.)

Evaluation Guidance: Score the Soldier GO if all steps are passed (P). Score the Soldier NO-GO if any step is failed (F). If the Soldier fails any step, show what was done wrong and how to do it correctly.

Evaluation Preparation: Ensure that all information, references, and equipment required to perform the task are available. Use the performance measures and the references to score the Soldier's performance. Inform the Soldier as to what he/she is required to perform IAW the task conditions and standards.

PERFORMANCE MEASURES	GO	NO-GO	N/A
1. Offloaded shelter transport bag.			
2. Placed shelter transport bag where shelter will be raised.			
3. Opened transport bag.			
4. Removed shelter repair kit, push poles, and cinched shelter.			
5. Uncinched the shelter.			
6. Unrolled the integrated floor.			
7. Placed integrated floor (green side up).			
8. Extended integrated floor, staked-down with stakes flush to the ground.			
9. Placed the bundled DRASH shelter on the center of the integrated floor with exterior side facing up and interior side facing down.			
10. Spreaded the DRASH shelter.			
11. Raised the DRASH shelter.			
12. Secured integrated floor.			
13. Secured the DRASH shelter.			

Supporting Reference(s):

Step Number	Reference ID	Reference Name	Required	Primary
	C0634	AMD Battery Command Post (BCP) Operations	No	No
	LOCAL SOP	LOCAL SOP	No	No
	USOP	Unit SOP	No	No

Environment: Environmental protection is not just the law but the right thing to do. It is a continual process and starts with deliberate planning. Always be alert to ways to protect our environment during training and missions. In doing so, you will contribute to the sustainment of our training resources while protecting people and the environment from harmful effects. Refer to FM 3-34.5 Environmental Considerations and GTA 05-08-002 ENVIRONMENTAL-RELATED RISK ASSESSMENT.

Safety: In a training environment, leaders must perform a risk assessment in accordance with FM 5-19, Risk Management. Leaders will complete a DA Form 7566 COMPOSITE RISK MANAGEMENT WORKSHEET during the planning and completion of each task and sub-task by assessing mission, enemy, terrain and weather, troops and support available-time available and civil considerations, (METT-TC). Note: During MOPP training, leaders must ensure personnel are monitored for potential heat injury. Local policies and procedures must be followed during times of increased heat category in order to avoid heat related injury. Consider the MOPP work/rest cycles and water replacement guidelines IAW FM 3-11.4, Multiservice Tactics, Techniques, and Procedures for Nuclear, Biological, and Chemical (NBC) Protection, FM 3-11.5, Multiservice Tactics, Techniques, and Procedures for Chemical, Biological, Radiological, and Nuclear Decontamination. Everyone is responsible for safety. A thorough risk assessment must be completed prior to every mission or operation.

Prerequisite Individual Tasks : None

Supporting Individual Tasks : None

Supported Individual Tasks :

Task Number	Title	Proponent	Status
441-096-1013	Emplace the Battery Command Post (BCP)	441 - Air Defense (Individual)	Approved
	Created from Template from 441-HHH-1013	441 - Air Defense (Individual)	Proposed
441-GGG-1019	Wrong Task, Delete	441 - Air Defense (Individual)	Analysis
441-HHH-1013	Emplace a Battery Command Post (BCP)	441 - Air Defense (Individual)	Analysis
441-GGG-1019	Perform Preventative Maintenance Checks and Services (PMCS) on a Multifunctional Information Distribution System (MIDS) Radio	441 - Air Defense (Individual)	Analysis

Supported Collective Tasks : None

ICTL Data :

ICTL Title	Personnel Type	MOS Data
MOS 14H - Air Defense (AD) Enhanced Early Warning Operator - SL1	Enlisted	MOS: 14H, Skill Level: SL1, Duty Pos: DQH